

BUILDING INSPECTION

Complies with Australian Standard AS 4349.1-2007 Inspection of Buildings Part 1: Pre-Purchase Inspections of Residential Buildings - Appendix C

Molly Mason

PROPERTY ADDRESS

26 Auster Crescent Sanctuary Point, 2540, Australia

Inspection Date: 22 Jun 2017, 10:52 AM to 2:18 PM Inspected by: Travis Reeves



Contents

				* 1
03	Description of Building	General Details	05	Summary of Inspection
06	Areas Inspected	Areas Not Inspected	80	Inspection
09	General Photographs 10	Defects & Safety Issues	11	Other Inspections & Reports Required
12	Conclusion & 13	Contact	14	Terms & Conditions
15	Definitions 16	Terminology	17	General Site Notes

03 Description of Building

Type of Building:

✓ Residential House

Style of Building:

✓ Conventional single storey

Number of Stories:

✓ Single Storey

Age of Building:

✓ 30-50 years old

Roof Covering:

✓ Concrete Roof Tiles

Roof Frame:

✓ Pine Roof Trusses

External Walls:

✓ Brick Veneer Walls

Floor Construction:

✓ Timber Floor on Brick Piers

Internal Walls:

✓ Timber Framed Walls

Building Tenancy:

Occupied

Building Furnished:

Yes

Building Frontage Faces:

South West





05 Summary of Inspection

Results of Building Inspection - Summary

	Found	Not Found
Safety Hazard	✓	
Major Defect	✓	
Minor Defect	✓	

Please refer to the report for explanations.

The overall condition of this residential Dwelling in the context of its age, type and general expectations of similar properties is Poor.

5.1 OVERVIEW:

a/ Retaining Walls:

The following summary below of **Satisfactory**, **Average and Poor** apply to the overall condition and to other areas of this Inspected Property if and when stated within this report document:

Not Applicable

ROOF EXTERIOR Poor
THE EXTERIOR: Average
THE SITE:

b/ Drainage: Poor c/ Outbuildings: Poor **THE SUB FLOOR SPACE**: Poor

THE ROOF VOID SPACE: Satisfactory
THE INTERIOR Average

OVERALL CONDITION Poor


Note: this summary must be read in conjunction with the full report. Should there be a discrepancy between the summary and the body of the report, the body of the report shall override.



06 Areas Inspected



The areas inspected were



07 Areas Not Inspected

The areas NOT accessible for any inspection were



08 Inspection

Kitchen

General View







Access Limitations

X Furniture, Closed Wardrobes/Cupboards, Clutter

Ceiling

No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

✓ No defects evident

Paint Condition

× Average condition

Floor

X Cracked tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





IMAGES

Sink

✓ No defects evident

Taps/Mixer

✓ No defects evident

Splashback

✓ No defects evident

Benchtop

✓ No defects evident

Top Cupboards

✓ No defects evident

Bottom Cupboards

✓ No defects evident

Food Cupboards

✓ No defects evident

Pantry

✓ No defects evident



Kickboards

✓ No defects evident

Blinds /Curtains/Shutters

X No blinds/ curtains evident at the time of the inspection

Window/s

✓ No defects evident

Fly Screens

✓ No defects evident

Skirting

✓ No defects evident


Architraves

✓ No defects evident

Meals Area

General View







Access Limitations

X Furniture, Clutter, Curtains and blinds

Ceiling

No defects evident

Ventilation

✓ No defects evident



Cornice /Scotia /Quad

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)





Walls

X Damage evident in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)







Paint Condition

X Average condition


Floor

Cracked tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Blinds/Curtains/Shutters

✓ No defects evident

External Exit Door/ Door Jamb / Door Furniture

Rollers worn suggest adjusting or replacing

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Security/Screen door

No defects evident

Architraves

✓ No defects evident


Skirting

✓ No defects evident

Lounge Room

General View







Access Limitations

X Furniture, Curtains and blinds, Clutter



Ceiling

✓ No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

✓ No defects evident

Paint Condition

Satisfactory condition

Floor

Cracked tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)





Door/ Door Jamb / Door Furniture

Door binding suggest shaving or cutting

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Blinds/Curtains/Shutters

× Average condition

Window/s

✓ No defects evident

Fly Screens

X Screen mesh damaged suggest replacing

Architraves


✓ No defects evident

Skirting

✓ No defects evident

Sunroom

General View





Access Limitations

X Clutter, Curtains and blinds, Furniture

Roof Covering

× Other

EXPLANATIONS

Comments: Significant rust & damage evident recommend

replacing sheets with rust & damage

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)













Roof Covering

× Other

EXPLANATIONS


IMAGES

Comments: Roof sheets lifting areas water penetration evident

Defect Significance: Mind

Defect Type: C (Water Penetration Damp Related)

IMAGES







Ceiling

X Damage evident in areas

EXPLANATIONS


Comments: Cracking, damage, water penetration evident in

areas

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)








IMAGES







Ventilation

✓ No defects evident

Walls

✓ No defects evident

Paint Condition

× Poor condition

Floor


X Cracked tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)





External Exit Door/ Door Jamb / Door Furniture

✓ No defects evident

Security/Screen door

✓ No defects evident

Blinds/Curtains/Shutters

× Poor condition - suggest replacing

Window/s

✓ No defects evident

Fly Screens

✓ No defects evident

Architraves

× Other

EXPLANATIONS

Comments: Missing in areas

Defect Significance: Minor

Defect Type: A (Damage)





Drainage

× Other

EXPLANATIONS

Comments: Inadequate drainage

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Front Entrance Area

General View







Access Limitations

 ➤ Closed Wardrobes/Cupboards, Clutter, Curtains and blinds



Ceiling

✓ No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

X Any other associated marks, indents, holes, scratches, cracks and/or poorly patched areas to some of the wall areas to this room can be rectified prior to the next time of repainting.

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)



IMAGES

Paint Condition

× Average condition

Floor

X Cracked tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Floor

X Drummy tiles evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Front External Exit Door/ Door Jamb / Door Furniture

No defects evident

Security/Screen door

No defects evident



Security/Screen door

✓ No defects evident

Linen Press

✓ No defects evident

Architraves

✓ No defects evident

Skirting

✓ No defects evident

Moisture

× Moisture identified

EXPLANATIONS

Reading: High 71 - 99

Comments: High moisture reading in linen press wall adjacent to

shower recess



IMAGES

Bedroom 1

General View





Access Limitations

IMAGES

X Clutter, Furniture, Closed Wardrobes/Cupboards, Curtains and blinds

Ceiling

✓ No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

✓ No defects evident

Paint Condition

X Average condition


Floor

X Stained & marked in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Blinds/Curtains/Shutters

× Average condition


Window/s

× Rollers require replacing

EXPLANATIONS

IMAGES

Defect Significance: Minor
Defect Type: A (Damage)



Fly Screens

X Screen mesh damaged suggest replacing



Door/ Door Jamb / Door Furniture

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)







Architraves


✓ No defects evident

Skirting

✓ No defects evident

Bedroom 2

General View





Access Limitations

X Furniture, Clutter, Curtains and blinds

Ceiling

X Damage evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)

IMAGES



Ventilation

No defects evident



Walls

X Damage evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)







Paint Condition

× Average condition

Floor


X Stained & marked in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)







Floor

X Floor movement evident, movement can be rectified the next time of re carpeting

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Blinds/Curtains/Shutters

× Average condition

Window/s

No defects evident



Fly Screens

X Screen mesh damaged suggest replacing

Door/ Door Jamb / Door Furniture

✓ No defects evident

Architraves

✓ No defects evident

Skirting

✓ No defects evident

Moisture

× Moisture identified

EXPLANATIONS

Reading: High 71 - 99

Comments: High moisture reading in wall adjacent to shower

recess





Bedroom 3

General View





Access Limitations

X Clutter, Curtains and blinds, Closed Wardrobes/Cupboards, Furniture

Ceiling

× Other

EXPLANATIONS

Comments: Works incomplete

Defect Significance: Minor

Defect Type: A (Damage)

IMAGES





Ventilation

No defects evident



Cornice /Scotia /Quad

× Other


EXPLANATIONS

Comments: Works incomplete

Defect Significance: Minor

Defect Type: A (Damage)







Paint Condition

× Poor condition

Floor

✓ No defects evident

Blinds/Curtains/Shutters

X Average condition

Window/s

× Other

EXPLANATIONS

Comments: Does not operate as intended suggest maintenance

Defect Significance: Minor

Defect Type: A (Damage)





Fly Screens

No defects evident

Door/ Door Jamb / Door Furniture

X Rollers worn suggest adjusting or replacing

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)

IMAGES



External Exit Door/ Door Jamb / Door Furniture

No defects evident



Security/Screen door

✓ No defects evident

Robe

✓ No defects evident

Architraves

✓ No defects evident

Skirting

✓ No defects evident

Main Bathroom

General View

















© 2017 Inspection Apps Pty Ltd. Produced by Inspection Apps under Licence to East Coast Building Inspections ABN 41 691 392 660

Access Limitations

X Closed Wardrobes/Cupboards, Curtains and blinds, Clutter

Ceiling

X Mould growth evident in some areas – suggest a thorough clean and repaint with mould resistant paint

EXPLANATIONS

Comments: Paint flaking evident in areas

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)





Exhaust fan / Heat light visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

✓ No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

× Other

EXPLANATIONS

Comments: Paint peeling in areas

Defect Significance: Minor

Defect Type: A (Damage)







Paint Condition

X Average condition

Wall Tiles

✓ No defects evident

Bathroom Floor Tiles

X Drummy tiles evident

EXPLANATIONS

Comments: Movement evident in areas

Defect Significance: Major

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,


decay)











Shower Wall Tiles

X Cracked tiles evident

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)

IMAGES



Shower Wall Tiles

X Minor re-grouting required

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)



Shower Floor

X Re-seal at wall and floor junction

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Shower Floor

Cracked tiles evident

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)







Shower Screen

✓ No defects evident

Shower Recess Under Water Test

X Evident of shower recess leak in subfloor

EXPLANATIONS

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)







IMAGES





Taps/Mixer Shower

No defects evident

Shower Head

No defects evident



Bath

✓ No defects evident

Bath Splashback

✓ No defects evident

Bath Side Tiles

✓ No defects evident

Taps/Mixer Bath

✓ No defects evident

Basins

✓ No defects evident

Vanity Cupboard

✓ No defects evident

Taps/Mixer Vanity

✓ No defects evident

Splashback Tiles

X Re-seal at wall and basin junction


EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

IMAGES



Fixtures

No defects evident



Pan and Cistern

No defects evident

Door/ Door Jamb / Door Furniture

Door binding suggest shaving or cutting

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)



IMAGES

Door/ Door Jamb / Door Furniture

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)





Blinds/Curtains/Shutters

X Poor condition - suggest replacing

Window/s

✓ No defects evident

Fly Screens

✓ No defects evident

Architraves

✓ No defects evident

Laundry

General View

IMAGES







© 2017 Inspection Apps Pty Ltd. Produced by Inspection Apps under Licence to East Coast Building Inspections ABN 41 691 392 660

Access Limitations

X Furniture, Closed Wardrobes/Cupboards, Curtains and blinds

Ceiling

✓ No defects evident

Ventilation

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Walls

✓ No defects evident

Paint Condition

X Average condition

Floor

✓ No defects evident

Tub

✓ No defects evident

Splashback

✓ No defects evident

Taps/Mixer Tub

✓ No defects evident

Taps Washing Machine

✓ No defects evident

Fixtures

✓ No defects evident

Pan and Cistern

✓ No defects evident

Blinds/Curtains/Shutters

× Average condition

Window/s

No defects evident

Fly Screens

✓ No defects evident



Door/ Door Jamb / Door Furnitur

Door binding suggest shaving or cutting

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





IMAGES

External Exit Door/ Door Jamb / Door Furniture

✓ No defects evident

Security/Screen door

✓ No defects evident

Laundry Cupboard

No defects evident

Architraves

✓ No defects evident

Services

General View

Access Limitations

× Vegetation, Clutter

Water meter visually inspected not tested. A licensed plumber should be consulted for further advice, if required.

× Other

EXPLANATIONS

Comments: Suggest removing vegetation

Defect Significance: Minor





External plumbing tap fitting visually inspected not tested. A licensed plumber should be consulted for further advice, if required.

No defects evident



Electricty main to building visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

No defects evident

Electricty meter box visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

✓ No defects evident

External light fittings. A licensed electrician should be consulted for further advice, if required.

× Poor condition

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)





Nbn box to house visually inspected not tested. A licensed telstra technician should be consulted for further advice, if required.

Not located

EXPLANATIONS

Defect Significance: Further Investigation

Hot water system visually inspected not tested. Hot water units with storage tanks must have the temperature set above 60 degrees to prevent bacteria forming within the tank and unit itself A licensed plumber/electrician should be consulted for further advice, if required.

We recommended alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Defect Significance: Minor





Water heater. A licensed plumber/ electrician should be consulted for further advice, if required.

Electric hot water

EXPLANATIONS

Comments:

315ltr water capacity







Tv antenna visually inspected not tested. A licensed technician should be consulted for further advice, if required.

✓ No defects evident

Foxtel antenna visually inspected not tested. A licensed technician should be consulted for further advice, if required.

No defects evident



A/C indoor unit visually inspected not tested.A dwellings A/C units are not tested at the time of this visual prepurchase inspection. We recommend the unit if evident to this property be serviced annually and its return air filters be cleaned on a regular basis as per the manufacturer's specifications. A licensed electrician should be consulted for further advice, if required.

✓ No defects evident

A/C outdoor unit visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

We recommended alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Defect Significance: Minor





Fire place / combustion heater unit visually inspected not tested. A fire safety consultant should be consulted for further advice, if required.

No defects evident

Oven/stove visually inspected not tested. A licensed electrician or plumber should be consulted for further advice, if required.

No defects evident

Cooktop visually inspected not tested. A licensed electrician or plumber should be consulted for further advice, if required.

No defects evident

Rangehood /Exhaust Fan visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

No defects evident

Dishwasher visually inspected not tested. A licensed electrician or plumber should be consulted for further advice, if required.

No defects evident



Internal electrical power points / switches / light fittings visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

✓ No defects evident

Phone and data cables. A licensed technician should be consulted for further advice, if required.

No defects evident

Smoke Detectors

General View



Smoke Detectors

X AS 3786 − Advises, that Smoke detectors are required for all buildings where people sleep. It is recommended that an Electrician be consulted to seek advice on these detectors. Smoke detectors must be ceiling mounted and not wall mounted.

Roof Void Space

General View









Access Limitations

X Insulation, The low pitch is eave areas, The low pitch in areas, Valley series timber truss sections

The roof void cleanliness

✓ No defects evident

Roof Structure

No defects evident

Common Roof Truss

✓ No defects evident

Top Chord Roof Truss

No defects evident



Truss Web Roof Truss

No defects evident

Cantilever Web Roof Truss

✓ No defects evident

Bottom Chord Roof Truss

✓ No defects evident

Insulation

× Other

EXPLANATIONS


Comments: Insulation may contain asbestos recommend

asbestos testing

Defect Significance: Further Investigation

Defect Type: F (Installation, including omissions)







Insulation

All types of ceiling insulation installation are to comply with the current Australian Standards AS/ NZS3000:2007 in relation to Downlights, Exhaust fans, IXL Heater/Fan Light units and Range Hood units

EXPLANATIONS

Defect Significance: Safety Hazard
Defect Type: E (Operational)





Reflective Foil

No defects evident

Whirlybird

✓ No defects evident


Electrical cables visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

X Exposed wires suggest using a licensed electrician to fix issues before use

EXPLANATIONS

Defect Significance: Safety Hazard
Defect Type: E (Operational)

IMAGES







Phone and data cables. A licensed technician should be consulted for further advice, if required.

× Other

EXPLANATIONS

Comments: Cover removed suggest re-fitting

Defect Significance: Minor

A (Damage) Defect Type:

IMAGES






Garage

General View

IMAGES



Access Limitations



× Clutter



Wall Coverings External

× Not checked

Roof Structure

✓ No defects evident

Ceiling

✓ No defects evident

Cornice /Scotia /Quad

✓ No defects evident

Wall Coverings Internal

× Incomplete works

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)



IMAGES

Paint Condition

× Poor condition

Concrete Floor

✓ No defects evident

Front Roller Doors

✓ No defects evident

Granny Flat

General View





Access Limitations

× Clutter

Roof Covering

X Roof sheets coating shows signs of deterioration suggest sealing for further weather protection

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

IMAGES







Roof Screws / Nails

× Other

EXPLANATIONS

Comments: Rust evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Ridges

× Other


EXPLANATIONS

Comments: Not installed in a tradesman like manor

Defect Significance: Minor

Defect Type: A (Damage)







Barge capping

No defects evident

Bargeboard

X Significant decay evident

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

IMAGES





Gutters

Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Comments: Gutters coming away from fascia boards

Defect Significance: Mind

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)







IMAGES





Downpipes

We recommend connection to storm water or alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage


EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)







Eaves

× Other

EXPLANATIONS

Comments: Not completed in a tradesman like manor

Defect Significance: Minor
Defect Type: A (Damage)







© 2017 Inspection Apps Pty Ltd.

Produced by Inspection Apps under Licence to
East Coast Building Inspections ABN 41 691
392 660

Eaves

Sagging of lining evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Scotia/Quad/Storm Molding

X Sagging evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Wall coverings external

Damaged evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)

IMAGES









IMAGES





Roof Structure

× Other

EXPLANATIONS

Comments: Flat roof construction could not be accessed for

inspection

Defect Significance: Further Investigation Defect Type: E (Operational)







Ceiling

× Water damage evident

EXPLANATIONS

Comments: Water penetration evident

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)

IMAGES





Cornice

✓ No defects evident



Wall coverings internal

X Any other associated marks, indents, holes, scratches, cracks and/or poorly patched areas to some of the wall areas to this room can be rectified prior to the next time of repainting.

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)







Wall coverings internal

X Moderate cracks were located

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)









Paint Condition

× Poor condition

Tiled floor

× Other

EXPLANATIONS

Comments: Cracked & loose tiles evident in areas

Defect Significance: Minor
Defect Type: A (Damage)







IMAGES





Tiled floor

× Other

EXPLANATIONS

Comments: Drummy tiles evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)







Blinds/CurtainsShutters

× Average condition

Window/s

★ Timber window frame – wood decay

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)







Window/s

× Other

EXPLANATIONS

Comments: Suggest maintenance

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)









Side entrance door

X Door damaged

EXPLANATIONS

Comments: Suggest replacing

Defect Significance: Minor

Defect Type: A (Damage)







Side entrance door

× Other

EXPLANATIONS

Comments: Door jamb damaged

Defect Significance: Minor

Defect Type: A (Damage)





Security/screen door

× Other

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

IMAGES



Architraves

Separating from wall is evident

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)



Skirting

X Water damage evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

IMAGES



Moisture

Moisture identified

EXPLANATIONS

Reading: High 71 - 99

Comments: High moisture reading in all walls to granny flat





Front Verandah

General View







Access Limitations

× Vegetation, Clutter

Rafters/Beams

✓ No defects evident

Ceiling

✓ No defects evident

Columns / Posts

✓ No defects evident



Paint Condition

X Average condition

Stairs

✓ No defects evident

Brick wall

✓ No defects evident


Drainage

✓ No defects evident

Rear Patio

General View







Access Limitations

× Vegetation, Clutter

Roof Covering

× Other


EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)





Roof Screws / Nails

✓ No defects evident

flashings

× Other

EXPLANATIONS

Comments: Flashing not installed in a tradesman like manor

Defect Significance: Minor
Defect Type: A (Damage)





Gutters

Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Comments: Gutters do not operate as intended suggest

replacing

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)





Downpipes

> Downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Rafters/Beams

Significant wood decay evident

EXPLANATIONS

Comments: Recommend replacing

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)



Columns / Posts

× Other

EXPLANATIONS

Comments: Post not plumb recommend straightening

Defect Significance: Minor

Defect Type: A (Damage)



IMAGES



× Poor condition



Concrete Floor

X Concrete has cracks in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)







Stairs

✓ No defects evident

Drainage

Inadequate drainage

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Outbuilding 1

General View





Access Limitations

× Vegetation, Clutter

Roof Covering

× Other

EXPLANATIONS

Comments: Suggest removing vegetation

Defect Significance: Minor
Defect Type: A (Damage)





Timber/Metal Structural Components

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)



IMAGES

Doors

X Door does not operate as intended

EXPLANATIONS

Comments: Suggest maintenance

Defect Significance: Minor

Defect Type: A (Damage)





Concrete Floor

× Other

EXPLANATIONS

Comments: Recommend removing builders waste

Defect Significance: Safety Hazard

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Drainage

X Inadequate drainage

EXPLANATIONS


Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Outbuilding 2

General View

IMAGES



Access Limitations

X Clutter, Vegetation

Timber/metal structural components

× Other

EXPLANATIONS

Comments: Damage evident recommend removal

Defect Significance: Safety Hazard Defect Type: A (Damage)





Exterior

General View

IMAGES



Access Limitations

× Vegetation, Clutter

Eaves

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)





Eaves

X Suggest painting for further weather protection

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Scotia/Quad/Storm Molding

X Sagging evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Cover Strips

No defects evident

Timber Trims

X Sagging evident in some areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Exterior Brick/Render Finish

Cracking evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: A (Damage)





Exterior Brick/Render Finish

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)



IMAGES

Windows

✓ No defects evident

Windows Trims

✓ No defects evident



Window Sills

✓ No defects evident

Doors

✓ No defects evident

Doors

✓ No defects evident

Doors Trims

× Other


EXPLANATIONS

Comments: Missing in areas

Defect Significance: Minor

Defect Type: A (Damage)





Door Sills

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)





Paint Condition

× Poor condition


Weep Holes

Weep Holes: Relating to concrete slab properties and also multi-level properties of brick construction. All of the weep holes are to be left completely exposed, unobstructed and clean at all times. They must be BCA code and Australian Standard compliant in relation to the time as to when the building was first built. Blocked, missing and obscured weep holes can and will cause further dampness problems within the building's interior and within the wall cavity areas. This also includes wall areas above windows and doors are to be BCA code compliant. In recent years weep holes are required to be put into place to the underside of window sills to all windows over .900mm in width and be no more than at 1.2metre centres.

EXPLANATIONS

Defect Significance: Minor

Defect Type: E (Operational)







© 2017 Inspection Apps Pty Ltd.

Produced by Inspection Apps under Licence to
East Coast Building Inspections ABN 41 691
392 660


Vents

X Vents are obstructed, Termites can enter cavity walls undetected

EXPLANATIONS

Defect Significance: Minor

Defect Type: E (Operational)



IMAGES

Site

General View

IMAGES





Access Limitations

× Vegetation, Clutter



The Site Cleanliness

X Builders waste suggest removing, House hold waste suggest removing

Driveway

X Gravel driveway is washed and eroded in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Driveway

Cracks evident in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)







Mail Box

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor



IMAGES

Paths

× Other

EXPLANATIONS

Comments: Undulating concrete is a trip hazard

Defect Significance: Safety Hazard
Defect Type: A (Damage)





Paths

X Concrete paths cracked in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)

IMAGES





Stairs

✓ No defects evident

Brick Wall Fencing

× Other

EXPLANATIONS

Comments: Significant cracking evident in areas

Defect Significance: Safety Hazard Defect Type: A (Damage)



IMAGES

Brick Wall Fencing

× Other

EXPLANATIONS

Comments: Damage evident in areas

Defect Significance: Minor

Defect Type: A (Damage)







Timber Pailing Gates

× Other

EXPLANATIONS

Comments: Significant wood decay evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)









Timber Pailing Gates

X Gate/s do not operate as intended

EXPLANATIONS

Comments: Wood decay & damage evident suggest replacing

Defect Significance: Minor
Defect Type: A (Damage)

IMAGES



Colourbond Fencing

Colorbond fence posts require straightening

EXPLANATIONS

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)





Fencing

× Other

EXPLANATIONS

Comments : Suggest removal Defect Significance: Safety Hazard

Defect Type: B (Distortion, Warping, Twisting)

IMAGES





Clothes Line


X Does not operate as intended

EXPLANATIONS

Comments: Damaged suggest replacing

Defect Significance: Minor







Rafters/Beams/Posts

IMAGES

× Other

EXPLANATIONS

Comments: Recommend removing structure

Defect Significance: Safety Hazard

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)





Tree's & Branches

X All or any trees associated to this property are to be assessed by an Arborist for their strength and in the event of any issues then these issues are to be dealt with immediately



Stored Timbers/Fire Wood

X Stored Timbers/fire wood should be removed or raised as there are conducive for termites

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)







Drainage

This site has inadequate surface inlet drainage. We recommend that additional site surface run off inlet and or diversion drainage be put into place around this property to protect this dwellings foundation materials.

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Sub Floor

General View



IMAGES



Access Limitations

× Vegetation, Clutter

The sub floor cleanliness

(Stored timbers within a sub floor area will form a "Conducive" condition to pending and possible termite attack.), Building waste

Flooring

× Other

EXPLANATIONS

Comments: Mould growth evident in areas

Defect Significance: Safety Hazard

Defect Type: C (Water Penetration Damp Related)







Main Bathroom Floor

X Water damage evident in areas

EXPLANATIONS

Comments: Water penetration evident from shower recess

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)

IMAGES





Kitchen Floor

Water damage evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)







Laundry Floor


× Water damage evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)







Bearers & Joists

No defects evident



Ant Capping

× Ant capping inadequate

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Piers

No defects evident

Brick Wall

X Rising damp evident in areas

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)









Ventilation

Ventilation inadequate

IMAGES

EXPLANATIONS

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)

Drainage

Inadequate drainage rectification is required

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Foundation Covering

X Significant mould is evident is areas

EXPLANATIONS

Defect Significance: Safety Hazard

Defect Type: C (Water Penetration Damp Related)







IMAGES



Sewer drainage connections visually inspected not tested. A licensed plumber should be consulted for further advice, if required.

✓ No defects evident

Water pipes visually inspected not tested. A licensed plumber should be consulted for further advice, if required.

✓ No defects evident

Electrical cables visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

✓ No defects evident

Sub floor door


✓ No defects evident



Roof Exterior

General View







IMAGES





Access Limitations

× Vegetation

Ridges

✓ No defects evident

Roof Covering

X Roof tiles coating shows signs of deterioration suggest sealing for further weather protection

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)







Roof Covering

★ Tiles require re-fitting in areas

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)









Roof Covering

There are several tiles with chipped corners

EXPLANATIONS

Defect Significance: Minor
Defect Type: A (Damage)







Valleys

✓ No defects evident

Gable End

✓ No defects evident

Lead Flashings

✓ No defects evident

Flashings

× Other

EXPLANATIONS

Comments: Flashing lifting & damage in areas

Defect Significance: Minor

Defect Type: A (Damage)











Chimney/Flue

No defects evident

Drain waste vent

✓ No defects evident

Whirlybird

✓ No defects evident

Barge Capping

✓ No defects evident



Bargeboard



EXPLANATIONS

Comments: Cracking & significant decay evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)
















IMAGES

Fascia

X Suggest paint for further weather protection

EXPLANATIONS

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Gutters

We recommended guttering / down pipes & connection to storm water or alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Defect Significance: Minor







Gutters

Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage


EXPLANATIONS

IMAGES

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

IMAGES







IMAGES

Downpipes


> Downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

EXPLANATIONS

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

IMAGES











IMAGES

IMAGES





Asbestos and Mould

Asbestos

➤ Possible asbestos observed at site A Full Asbestos ID Report is available for \$250 for visual inspection \$349 for visual inspection + sample Lab test from \$99 per sample

Is your home or building built before 2000? if so it may contain asbestos.

You are thinking about renovating you must be aware. It's important for home owners and renovators to be aware of how to safely manage asbestos in & around the home.

Asbestos fibres were used widely in building materials before the mid 1980's. Your house was built or renovated before the mid 1980's, it's likely to contain asbestos cement building materials. Australia was one of the highest users per capita in the world up until the mid 1980's.

New South Wales use was discontinued in all fibro sheets and products by the mid 1980's. After this, asbestos continued to be used principally in friction products, for brake and clutch linings. Manufacture and use of asbestos products was banned nationally in Australia from 31 December 2003.

Some places where you will find It asbestos

Roof sheeting and capping

Guttering

Gables, eaves/soffits

Water pipes

Lagging on pipping

Flues

Exterior wall sheeting (flat or a weatherboard style)

Interior Wall sheeting

Interior Ceiling sheeting

Vinyl sheet flooring & glue

Floor sheeting

Carpet and tile underlays

Zelemite backing boards to the switchboards

Flexible building boards

Imitation brick cladding

Fencing

Carports and sheds

Waterproof membrane

Some window putty

Expansion joints

Window packing

Door packing

Packing under beams

Concrete form work

Importantly, if you suspect you have asbestos in your HOME, Don't cut it! Don't drill it! Don't drop it! Don't sand it! Don't cut it! Don't scrape it! Don't scrub it! Don't dismantle it! Don't water blast it! Don't demolish it! Don't dump it!

We recommended asbestos inspection & testing before renovating or demolishing.



Mould

➤ Observed at site
A Full Mould ID Report is available for \$250 for visual inspection
\$349 for visual inspection + sample
Lab test from \$99 per sample

Mould is part of a group of very common organisms called fungi that also include mushrooms and yeast. It is present virtually everywhere, both indoors and outdoors. Mould is the common word for any fungus that grows on food or damp materials. The colours can be black, grey, green, yellow, white or almost any colour.

It often looks like a stain or smudge and it may smell musty. In order to grow it needs moisture and a material it can live on. It then releases "spores" into the air which are small enough that people can actually breathe them in. Breathing in large amounts of these spores and the by-products they produce can negatively impact your health.

Mould may grow indoors in wet or moist areas lacking adequate ventilation, including subfloor areas, roof void, exteriors of buildings, walls/ wallpaper, ceilings, wet areas, bathroom tiles, carpets especially those with fiber backing, insulation material and wood. If moisture accumulates in a building mould growth will often occur.

Many different types exist and all have the potential to cause health problems. It is impossible to determine what type of mould is growing by visual inspection only, there are thousands of known species below are common types found in homes & businesses.

09 General Photographs















































10 Defects and Safety Issues

Safety Hazards in this Building:

Roof Void Space (Optional)

Insulation

X All types of ceiling insulation installation are to comply with the current Australian Standards AS/ NZS3000:2007 in relation to Downlights, Exhaust fans, IXL Heater/Fan Light units and Range Hood units

Explanation

Comments (Optional):

Defect Significance: Safety Hazard
Defect Type: E (Operational)

Electrical cables visually inspected not tested. A licensed electrician should be consulted for further advice, if required.

X Exposed wires suggest using a licensed electrician to fix issues before use

Explanation

Comments (Optional):

Defect Significance: Safety Hazard
Defect Type: E (Operational)

Outbuilding 1 (Optional)

Concrete Floor

X Other

Explanation

Comments (Optional): Recommend removing builders waste

Defect Significance: Safety Hazard

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)



Outbuilding 2 (Optional)

Timber/metal structural components

X Other

Explanation

Comments (Optional):

Defect Significance:

Defect Type:

Damage evident recommend removal
Safety Hazard
A (Damage)

Site (Optional)

Paths

X Other

Explanation

Comments (Optional):

Defect Significance:

Defect Type:

Undulating concrete is a trip hazard

Safety Hazard

A (Damage)

Brick Wall Fencing

X Other

Explanation

Comments (Optional):

Defect Significance:

Significant cracking evident in areas
Safety Hazard
A (Damage)

Fencing

X Other

Explanation

Comments (Optional):

Defect Significance:

Defect Type:

Suggest removal

Safety Hazard

B (Distortion, Warping, Twisting)



Rafters/Beams/Posts



Explanation

Comments (Optional):

Defect Significance:

Defect Type:

Recommend removing structure
Safety Hazard

D (Material Deterioration: rusting

D (Material Deterioration: rusting, rotting, corrosion, decay)

Sub Floor (Optional)

Flooring

X Other

Explanation

Comments (Optional): Mould growth evident in areas

Defect Significance: Safety Hazard

Defect Type: C (Water Penetration Damp Related)

Foundation Covering

X Significant mould is evident is areas

Explanation

Comments (Optional):

Defect Significance: Safety Hazard

Defect Type: C (Water Penetration Damp Related)

Major Defects in this Building:

Sunroom (Optional)

Ceiling

X Damage evident in areas

Explanation

Comments (Optional): Cracking, damage, water penetration evident in

areas

Defect Significance: Major



Main Bathroom (Optional)

Bathroom Floor Tiles

X Drummy tiles evident

Explanation

Comments (Optional): Movement evident in areas

Defect Significance: Majo

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Major

Shower Recess Under Water Test

X Evident of shower recess leak in subfloor

Explanation

Comments (Optional):

Defect Significance:

Defect Type: C (Water Penetration Damp Related)

Granny Flat

Ceiling

X Water damage evident

Explanation

Comments (Optional): Water penetration evident

Defect Significance: Major

Defect Type: C (Water Penetration Damp Related)

Sub Floor (Optional)

Main Bathroom Floor

X Water damage evident in areas

Explanation

Comments (Optional): Water penetration evident from shower recess

Defect Significance: Maj



Ventilation

X Ventilation inadequate

Explanation

Comments (Optional): Defect Significance: Defect Type:

Major C (Water Penetration Damp Related)

Minor and Other Defects in this Building:

Kitchen (Optional)

Floor

X Cracked tiles evident in some areas

Explanation

Comments (Optional): Defect Significance:

Minor

Defect Type:

A (Damage)

Meals Area (Optional)

Cornice /Scotia /Quad

X Other

Explanation

Defect Type:

Comments (Optional): Damage evident in areas

Defect Significance:

A (Damage)

Minor

Walls

X Damage evident in areas

Explanation

Comments (Optional):

Defect Significance:
Defect Type:

Minor A (Damage)



Floor

X Cracked tiles evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)

External Exit Door/ Door Jamb / Door Furniture

X Rollers worn suggest adjusting or replacing

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)

Lounge Room (Optional)

Floor

X Cracked tiles evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)

Door/ Door Jamb / Door Furniture

X Door binding suggest shaving or cutting

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)



Sunroom (Optional)

Roof Covering

X Other

Explanation

Comments (Optional): Significant rust & damage evident recommend

replacing sheets with rust & damage

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Roof Covering

× Other

Explanation

Comments (Optional): Roof sheets lifting areas water penetration evident

Defect Significance: Min

Defect Type: C (Water Penetration Damp Related)

Floor

X Cracked tiles evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Architraves

× Other

Explanation

Comments (Optional): Missing in areas

Defect Significance:

Defect Type:

Minor

A (Damage)

Drainage

X Other

Explanation

Comments (Optional): Inadequate drainage

Defect Significance: Minor



Front Entrance Area (Optional)

Walls

X Any other associated marks, indents, holes, scratches, cracks and/or poorly patched areas to some of the wall areas to this room can be rectified prior to the next time of repainting.

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Floor

X Cracked tiles evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Floor

X Drummy tiles evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Bedroom 1 (Optional)

Floor

X Stained & marked in areas

Explanation

Comments (Optional):



Window/s

X Rollers require replacing

Explanation

Comments (Optional):

Defect Significance:

Minor

Defect Type:

A (Damage)

Door/ Door Jamb / Door Furniture

X Other

Explanation

Comments (Optional):

Defect Significance:

Defect Type:

Damage evident in areas

Minor

A (Damage)

Bedroom 2 (Optional)

Ceiling

X Damage evident in areas

Explanation

Comments (Optional):

Defect Significance:

Minor

Defect Type:

A (Damage)

Walls

X Damage evident in areas

Explanation

Comments (Optional):

Defect Significance:

Minor

Defect Type:

A (Damage)

Floor

X Stained & marked in areas

Explanation

Comments (Optional):

Defect Significance:

Minor

Defect Type:

A (Damage)



Floor

X Floor movement evident, movement can be rectified the next time of re carpeting

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Bedroom 3 (Optional)

Ceiling

X Other

Explanation

Comments (Optional): Works incomplete

Defect Significance: Minor
Defect Type: A (Damage)

Cornice /Scotia /Quad

X Other

Explanation

Comments (Optional): Works incomplete

Defect Significance: Minor
Defect Type: A (Damage)

Window/s

X Other

Explanation

Comments (Optional): Does not operate as intended suggest maintenance

Defect Significance: Minor
Defect Type: A (Damage)

Door/ Door Jamb / Door Furniture

X Rollers worn suggest adjusting or replacing

Explanation

Comments (Optional):



Main Bathroom (Optional)

Ceiling

X Mould growth evident in some areas – suggest a thorough clean and repaint with mould resistant paint

Explanation

Comments (Optional): Paint flaking evident in areas

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Walls

X Other

Explanation

Comments (Optional): Paint peeling in areas

Defect Significance: Minor
Defect Type: A (Damage)

Shower Wall Tiles

X Cracked tiles evident

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Shower Wall Tiles

X Minor re-grouting required

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Shower Floor

X Re-seal at wall and floor junction

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)



Shower Floor

X Cracked tiles evident

Explanation

Comments (Optional):

Defect Significance:
Defect Type:

Splashback Tiles

X Re-seal at wall and basin junction

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Minor A (Damage)

Door/ Door Jamb / Door Furniture

X Door binding suggest shaving or cutting

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Door/ Door Jamb / Door Furniture

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

Laundry (Optional)

Door/ Door Jamb / Door Furnitur

Door binding suggest shaving or cutting

Explanation

Comments (Optional):



Services (Optional)

Water meter visually inspected not tested. A licensed plumber should be consulted for further advice, if required.

× Other	
Explanation Comments (Optional): Defect Significance:	Suggest removing vegetation Minor
External light fittings. A licensed electrician should be consulted for further advice, if required.	
× Poor condition	
Explanation Comments (Optional): Defect Significance: Defect Type:	Minor A (Damage)
Hot water system visually inspected not tested. Hot water units with storage tanks must have the temperature set above 60 degrees to prevent bacteria forming within the tank and unit itself A licensed plumber/electrician should be consulted for further advice, if required.	
We recommended alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage	
Explanation Comments (Optional): Defect Significance:	Minor
A/C outdoor unit visually inspected not tested. A further advice, if required.	licensed electrician should be consulted for
We recommended alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage	
Explanation	



Comments (Optional): Defect Significance:

Minor

Roof Void Space (Optional)

Phone and data cables. A licensed technician should be consulted for further advice, if required.

X Other

Explanation

Comments (Optional): Cover removed suggest re-fitting

Defect Significance: Minor
Defect Type: A (Damage)

Granny Flat

Roof Covering

X Roof sheets coating shows signs of deterioration suggest sealing for further weather protection

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Roof Screws / Nails

X Other

Explanation

Comments (Optional): Rust evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Ridges



Explanation

Comments (Optional): Not installed in a tradesman like manor



Bargeboard

X Significant decay evident

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Gutters

X Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional): Gutters coming away from fascia boards

Defect Significance: Mine

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Downpipes

We recommend connection to storm water or alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Eaves

X Other

Explanation

Comments (Optional): Not completed in a tradesman like manor

Defect Significance: Minor
Defect Type: A (Damage)

Eaves

Sagging of lining evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)



Scotia/Quad/Storm Molding

X Sagging evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Wall coverings external

X Damaged evident in areas

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Wall coverings internal

X Any other associated marks, indents, holes, scratches, cracks and/or poorly patched areas to some of the wall areas to this room can be rectified prior to the next time of repainting.

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Wall coverings internal

X Moderate cracks were located

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Tiled floor

X Other

Explanation

Comments (Optional): Cracked & loose tiles evident in areas



Tiled floor

X Other

Explanation

Comments (Optional): Drummy tiles evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Window/s

X Timber window frame - wood decay

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Window/s

X Other

Explanation

Comments (Optional): Suggest maintenance

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Side entrance door

X Door damaged

Explanation

Comments (Optional): Suggest replacing

Defect Significance: Minor
Defect Type: A (Damage)

Side entrance door

X Other

Explanation

Comments (Optional): Door jamb damaged



Security/screen door

X Other

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Architraves

X Separating from wall is evident

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Skirting

X Water damage evident in areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Rear Patio

Roof Covering

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

flashings

X Other

Explanation

Comments (Optional): Flashing not installed in a tradesman like manor



Gutters

X Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional): Gutters do not operate as intended suggest

replacing

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Downpipes

> Downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Rafters/Beams

X Significant wood decay evident

Explanation

Comments (Optional): Recommend replacing

Defect Significance: Mino

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Columns / Posts

X Other

Explanation

Comments (Optional): Post not plumb recommend straightening

Defect Significance: Minor

Defect Type: A (Damage)

Concrete Floor

X Concrete has cracks in areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)



Drainage

X Inadequate drainage

Explanation

Comments (Optional):

Defect Significance:

Defect Type: C (Water Penetration Damp Related)

Minor

Outbuilding 1 (Optional)

Roof Covering

X Other

Explanation

Comments (Optional): Suggest removing vegetation

Defect Significance: Minor
Defect Type: A (Damage)

Timber/Metal Structural Components

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

Doors

X Door does not operate as intended

Explanation

Comments (Optional): Suggest maintenance

Defect Significance: Minor
Defect Type: A (Damage)

Drainage

X Inadequate drainage

Explanation

Comments (Optional):

Defect Significance: Minor



Exterior (Optional)

Eaves

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

Eaves

X Suggest painting for further weather protection

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Scotia/Quad/Storm Molding

X Sagging evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Timber Trims

X Sagging evident in some areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Exterior Brick/Render Finish

X Cracking evident in areas

Explanation

Comments (Optional):



Exterior Brick/Render Finish

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

Doors Trims



Explanation

Comments (Optional): Missing in areas

Defect Significance: Minor
Defect Type: A (Damage)

Door Sills



Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor
Defect Type: A (Damage)

Weep Holes

Weep Holes: Relating to concrete slab properties and also multi-level properties of brick construction. All of the weep holes are to be left completely exposed, unobstructed and clean at all times. They must be BCA code and Australian Standard compliant in relation to the time as to when the building was first built. Blocked, missing and obscured weep holes can and will cause further dampness problems within the building's interior and within the wall cavity areas. This also includes wall areas above windows and doors are to be BCA code compliant. In recent years weep holes are required to be put into place to the underside of window sills to all windows over .900mm in width and be no more than at 1.2metre centres.

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: E (Operational)

Vents

X Vents are obstructed, Termites can enter cavity walls undetected

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: E (Operational)



Site (Optional)

Driveway

X Gravel driveway is washed and eroded in areas

Explanation

Comments (Optional):

Defect Significance:

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Minor

Driveway

X Cracks evident in areas

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Mail Box

X Other

Explanation

Comments (Optional): Damage evident in areas

Defect Significance: Minor

Paths

X Concrete paths cracked in areas

Explanation

Comments (Optional):

Defect Significance: Minor
Defect Type: A (Damage)

Brick Wall Fencing

× Other

Explanation

Comments (Optional): Damage evident in areas



Timber Pailing Gates

X Other

Explanation

Comments (Optional): Significant wood decay evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Timber Pailing Gates

X Gate/s do not operate as intended

Explanation

Comments (Optional): Wood decay & damage evident suggest replacing

Defect Significance: Minor
Defect Type: A (Damage)

Colourbond Fencing

X Colorbond fence posts require straightening

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: B (Distortion, Warping, Twisting)

Clothes Line

X Does not operate as intended

Explanation

Comments (Optional): Damaged suggest replacing

Defect Significance: Minor

Stored Timbers/Fire Wood

X Stored Timbers/fire wood should be removed or raised as there are conducive for termites

Explanation

Comments (Optional):

Defect Significance: Mino

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)



Drainage

X This site has inadequate surface inlet drainage. We recommend that additional site surface run off inlet and or diversion drainage be put into place around this property to protect this dwellings foundation materials.

Minor

Explanation

Comments (Optional):

Defect Significance:

Defect Type: C (Water Penetration Damp Related)

Sub Floor (Optional)

Kitchen Floor

X Water damage evident in areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Laundry Floor

X Water damage evident in areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Ant Capping

X Ant capping inadequate

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Brick Wall

X Rising damp evident in areas

Explanation

Comments (Optional):

Defect Significance: Mino



Drainage

X Inadequate drainage rectification is required

Explanation

Comments (Optional):

Defect Significance:

Defect Type: C (Water Penetration Damp Related)

Roof Exterior (Optional)

Roof Covering

X Roof tiles coating shows signs of deterioration suggest sealing for further weather protection

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Minor

Roof Covering

Tiles require re-fitting in areas

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)

Roof Covering

X There are several tiles with chipped corners

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: A (Damage)

Flashings



Explanation

Comments (Optional): Flashing lifting & damage in areas



Bargeboard

X Other

Explanation

Comments (Optional): Cracking & significant decay evident in areas

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Fascia

X Suggest paint for further weather protection

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: D (Material Deterioration: rusting, rotting, corrosion,

decay)

Gutters

We recommended guttering / down pipes & connection to storm water or alternate water diversion (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional):

Defect Significance: Minor

Defect Type: C (Water Penetration Damp Related)

Gutters

➤ Gutters & downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional):

Defect Significance: Minor



Downpipes

X Downpipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.) inadequate drainage

Explanation

Comments (Optional): Defect Significance:

Minor



11 Other Inspections and Reports Required

Further Inspections/Searches Recommended

Timber PPI Pest (termite) inspection	Smoke Alarm Certification	Electrical Inspection
Plumbing inspection	Property Valuation	Sewer Diagram
Final survey	Council approvals to be sought for the additions & alterations visible within this property	Home Owners Warranty
Mould identification & inspections	Asbestos identification & inspections	



12 Conclusion & Summary

The purpose of the inspection is to identify the major defects and safety hazards associated with the property at the time of the inspection. The inspection and reporting is limited to a visual assessment of the Building Members in accord with Appendix C AS4349.1-2007.

The overall condition of this building has been compared to similar constructed buildings of approximately the same age where those buildings have had a maintenance program implemented to ensure that the building members are still fit for purpose.

The incidence of Major Defects in this Residential Building as compared with similar Buildings is considered:

Typical

The incidence of Minor Defects in this Residential Building as compared with similar Buildings is considered:

High

The overall condition of this residential Dwelling in the context of its age, type and general expectations of similar properties is:

Poor

Overall Condition Comments:

It is recommended that confirmation be obtained by the relevant authorities that the structure being reported on the granny flat & the converted garage into the 3 bedroom has been approved for its intended use.

Shower leak was visibly evident at the time of this inspection in the main bathroom and we recommend all works be carried out by a qualified and licensed trades person and a warranty must be sought.

Gutters & down pipes are leaking at their joints in areas & need rectification. (Excessive leaking can cause "Conducive" conditions to possible termite attack.)

We recommend that additional site surface run off inlet and or diversion drainage be put into place around this property to protect this dwellings foundation materials.

The eave lining timber storm moulds: Gapping is an indication of possible settlement to this nominated area of the dwelling, therefore check the drainage of surface waters is adequate at these gapping points.

Any timbers that are in direct ground contact being in garden areas or the pergola, the awning, the carport or related item should be removed or relocated or treated unless evidence is provided that these timbers are of a treated or specific type suitable for its as applied application.

Floor movement: Floor movement evident, Movement can be rectified the next time of recarpeting.

Inadequate ant-capping must be replaced and installed as required. Ant-capping was inadequate and rusting in sections.

Stored timbers within a sub floor area will form a "Conducive" condition to pending and possible termite attack.

Cornice joint cracking and cornice separation may be visible in some of the room areas. This is only minor and is normally common settlement only, unless otherwise stated in the body of this report.

Any other associated marks, indents, holes, scratches, cracks and/or poorly patched areas to some of the wall and ceiling areas internally can be rectified prior to the next time of repainting.



Some of the doors need new door stops to be fitted to prevent wall and or door lock damage. (All types of ceiling insulation installation are to comply with the current Australian Standards AS/NZS3000:2007 in relation to Downlights, Exhaust fans, IXL Heater/Fan Light units and Range Hood units.)

AS 3786 – Advises, that Smoke detectors are required for all buildings where people sleep. It is recommended that an Electrician be consulted to seek advice on these detectors. Smoke detectors must be ceiling mounted and not wall mounted.

Smoke detectors are not tested at the time of this inspection. Therefore if unsure call a Licensed Electrician for further advice.

A dwellings A/C units are not tested at the time of this visual pre-purchase inspection. We recommend the unit if evident to this property be serviced annually and its return air filters be cleaned on a regular basis as per the manufacturer's specifications.

As a general comment, any A/C unit/s condensation drainage outlets must also be directed into or over an appropriate drainage inlet point, also with a clear hose only.

PC Appliances: (Dishwashers, Range Hoods, Ovens, Hot Plates & Microwave units are not tested in a visual pre purchase inspection as this is out of our area of expertise) Phone and data cables have been poorly laid on the ground. All cables in a roof loft area should not be subject to damage.) All cables in a roof loft area should not be subject to damage.)

The shower tap flanges should be sealed and then must be re-sealed annually to the wall tile surface for the prevention of internal wall damage.

Hot Water Services with storage tanks must not set below 60degrees to prevent bacteria forming in the system.

A clear hose should be fitted to the overflow pipe and redirected into an appropriate drainage inlet point, (A LICENSED PLUMBER SHOULD BE CONSULTED FOR FURTHER ADVICE, IF REQUIRED. The age of the existing unit is unknown.) (NOTE: we do not test the pressure relief valves on freestanding hot water units as this valve may break, seize or leak due to lack of testing over a period of time by the owners of properties.) NOTE: hot water units with storage tanks must have the temperature set above 60degrees to prevent bacteria forming within the tank and unit itself. A clear hose should be fitted to the overflow pipe and redirected into an appropriate drainage inlet point, (A LICENSED PLUMBER SHOULD BE CONSULTED FOR FURTHER ADVICE. IF REOUIRED.

Trees: Where trees are too close to the dwelling house, then this could affect the performance of the dwellings footings as the moisture levels change within the ground. A Geotechnical Engineer's Inspection can determine the foundation material and advice on the best course of action with regards to the trees. Council approval is required for the removal of trees. TREES: All or any trees associated to this property are to be assessed by an Arborist for their strength and in the event of any issues then these issues are to be dealt with immediately. Trees can cause issues to a dwellings foundations of they are within 3.0m of the dwellings exterior.

Verbal estimates if given are only opinions of costs of rectification. The knowledge, calculations and experience of the inspector are calculation only of possible costs that may be required. We accept no liability for any estimates provided throughout our inspection and report. It is essential you obtain independent prices from other qualified tradespeople for the works, if and when required.

Please Note: This is a general appraisal only and cannot be relied on its own - read the report in its entirety.

This Summary is supplied to allow a quick and superficial overview of the inspection results. This Summary is NOT the Report and cannot be relied upon on its own. This Summary must be read in conjunction with the full report and not in isolation from the report. If there should happen to be any discrepancy between anything in thie Report and anything in this summary, the information in the report shall override that in this summary.



13 Contact

We take this opportunity to thank you for your instructions.

If you have any queries, please do not hestitate to contact our inspector.

Yours faithfully,

Travis Reeves

East Coast Building Inspections

Sarah: 0422 081 023 Travis: 0457 649 622

ecbuildinspect@bigpond.com

eastcoastbuildinginspections.com.au

14 Terms & Conditions

Part 1: Purpose and Scope of Inspection

This report complies with Australian Standard AS4349.1 - 2007 Inspection of Buildings, Part 1: Pre-Purchase Inspections - Residential Buildings.

Inspection Agreement - Individual title property

Requirement for Inspection agreement AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

Purpose of Inspection

The purpose of the inspection is to provide advice to a prospective purchaser or other interested party regarding the condition of the property on the date and at the time of the inspection. The advice is limited to the reporting of the condition of the Building Elements in accord with Appendix B or C AS4349.1-2007 (Appendix B for Strata or Company Title and Appendix C for other residential buildings).

Important Information and Disclaimer

Any person who relies upon the contents of this report does so acknowledging that the following clauses both below **and** at the end of this report. These define the Scope and Limitations of the inspection and form an integral part of the report. Before you decide to purchase this property you should read and understand all of the information contained herein. It will help explain what is involved in a Residential Pre-Purchase Building Inspection Report, the difficulties faced by an inspector and why it is not possible to guarantee that a property is free of defects, latent or otherwise. This information forms an integral part of the report. If there is anything contained within this report that is not clear or you have difficulty understanding, please contact the inspector prior to acting on this report.

The extent and thoroughness of this inspection has been limited by our reading of what was reasonable by way of time, intrusion and risk of doing physical damage to the property being inspected. We have not inspected woodwork or other parts of the structure which are covered, unexposed or inaccessible and we are therefore unable to report that any such part of the structure is free from defect. Identification of hazardous materials or situations that may be in the building or on or near the property is outside the scope of this inspection. This report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law, and is not a warranty against problems developing with the building in the future. This report does not include the identification of unauthorised building work or of work not compliant with building regulations. With respect to minor defects, the inspection is limited to reporting on their overall extent. It is not intended to detail each and every individual minor defect or imperfection. This service is provided on an independent professional basis. It seeks to present a factual, unbiased and balanced assessment. We have no financial interest in any work that may be recommended or in any share of commission if the property is sold.

Scope of Inspection

The inspection comprised a visual assessment of the property to identify major defects and safety hazards, and to form an opinion regarding the general condition of the property at the time of inspection. An estimate of the cost of rectification of defects is outside the scope of the Standard and therefore does not form part of this report.



AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building and which is in reasonable condition, having been adequately maintained over the life of the building. This means that building being inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applicable at the time of the inspection.

What is reported on:

- The inspection includes subjective appraisal by an inspector competent to assess the condition of residential buildings. It involves a subjective assessment so different inspectors or even the same inspector on a different occasion may reach different conclusions
- The inspection comprises a visual assessment of the property to identify major defects and to form an opinion regarding the general condition of the property at the time of inspection.
- The following areas shall be inspected where applicable:
 - The interior of the building: ceilings; walls; floors; windows; doors & frames; kitchen;
 bathroom; WC; ensuite; laundry; stairs & damp problems
 - The exterior of the building: walls (including lintels, claddings, doors & windows); timber or steel frames & structures; chimneys; stairs; balconies, verandas, patios, decks, suspended concrete floors, balustrades
 - The roof exterior: roof (including tiles, shingles & slates, roof sheeting, gables, flashings);
 skylights, vents, flues; valleys; guttering; downpipes; eaves, fascias and barges
 - The roof space: roof covering; roof framing; sarking; party walls; insulation
 - The sub-floor space: timber floor (including supports, floor, ventilation, drainage, damp);
 suspended concrete floors
 - The property within 30m of the house and within the boundaries of the site: car accommodation, detached laundry, ablution facilities and garden sheds; retaining walls (where supporting other structures and landscaping retaining walls > 700mm high); paths & driveways; steps; fencing (excluding swimming pool fences); surface water (drainage effectiveness)

What is not reported on:

- general exclusions detailed in the standard AS 4349.1 2007
- Parts of a building that are under construction
- · The inspection is not intended to include rigorous assessment of all building elements in a property
- Defects that would only be apparent under particular weather conditions or when using particular fittings & fixtures
- · Defects not apparent due to occupancy or occupancy behavior eg non use of a leaking shower
- The inspection report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing with the building in the future
- · Unauthorized building work or of work not compliant with building regulations
- Title and ownership matters, matters concerning easements, covenants, restrictions, zoning certificates and all other law-related matters
- · Estimation of the cost of rectification of specific defects.
- Specifics excluded by the standard AS 4349.1 2007 Footings below ground, concealed damp-proof course, electrical installations, operation of smoke detectors, light switches and fittings, TV, sound and communication and security systems, concealed plumbing, adequacy of roof drainage as installed, gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming pools and associated filtration and similar equipment, the operation of fireplaces and solid fuel heaters, including chimneys and flues, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, ducted vacuum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, lead content, radon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators), soil conditions, control joints, sustainable development provisions, concealed framing-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furniture and accessories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, energy efficiency, lighting efficiency.

Special Requirements



It is acknowledged that there are no special requirements placed on this inspection that are outside the scope of the abovementioned Australian Standard.

Limitations

This report is limited to a visual inspection of areas where safe and reasonable access is available and access permitted on the date and at the time of inspection. The Inspection will be carried out in accordance with AS4349.1-2007. The purpose of the inspection is to provide advice to a prospective purchaser regarding the condition of the property at the date and time of inspection. Areas for Inspection shall cover all safe and accessible areas. It does not purport to be geological as to foundation integrity or soil conditions, engineering as to structural, nor does it cover the condition of electrical, plumbing, gas or motorised appliances. It is strongly recommended that an appropriately qualified contractor check these services prior to purchase.

As a matter of course, and in the interests of safety, all prospective purchasers should have an electrical report carried out by a suitably qualified contractor.

This report is limited to (unless otherwise noted) the main structure on the site and any other building, structure or outbuilding within 30m of the main structure and within the site boundaries including fences.

Safe and Reasonable Access

Only areas to which safe and reasonable access is available were inspected. The Australian Standard 4349.1 defines reasonable access as "areas where safe, unobstructed access is provided and the minimum clearances specified below are available, or where these clearances are not available, areas within the inspector's unobstructed line of sight and within arm's length. Reasonable access does not include removing screws and bolts to access covers." Reasonable access does not include the use of destructive or invasive inspection methods nor does it include cutting or making access traps or moving heavy furniture, floor coverings or stored goods.

Dimensions for Reasonable Access

Roof Interior - Access opening = 400 x 500 mm - Crawl Space = 600 x 600mm - Height accessible from a 3.6m ladder.

Roof Exterior - Must be accessible from a 3.6m ladder placed on the ground.



15 Definitions

High: The frequency and/or magnitude of defects are beyond the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Typical: The frequency and/or magnitude of defects are consistent with the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Low: The frequency and/or magnitude of defects are lower than the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Above Average: The overall condition is above that consistent with dwellings of approximately the same age and construction. Most items and areas are well maintained and show a reasonable standard of workmanship when compared with buildings of similar age and construction.

Average: The overall condition is consistent with dwellings of approximately the same age and construction. There will be areas or items requiring some repair or maintenance.

Below Average: The Building and its parts show some significant defects and/or poor non-tradesman like workmanship and/or long term neglect and/or defects requiring major repairs or reconstruction of major building elements.

Major Defect: Is a Defect requiring building works to avoid unsafe conditions, loss of function or further worsening of the defective item.

Minor Defect: Any Defect other than what is described as a major defect.

Accessible area: is any area of the property and structures allowing the inspector safe and reasonable access within the scope of the inspection.

Satisfactory: The areas inspected appear to be in serviceable and sound condition without any significant visible defects.

Average: The inspected areas evident require repairs and or maintenance which are consistent with the age of the property.

Poor: The areas inspected require major repairs and or replacement due to its age, poor maintenance, deterioration or not being completed to an acceptable standard of workmanship.

16.1 CLASSIFICATION OF DEFECTS AT THE TIME OF THIS INSPECTION:

Defects are categorized into 6 areas as described below.

These descriptions are clearly defined in AS4349.1-2007 Table 3.3 "Type of Defects."

- A Damage (visual disruption or breakage resulting in loss of value or the impairment of usefulness,)
- **B** Distortion, warping and twisting (a change in the shape of an image resulting from imperfections from its intended location,)
- **C** Water penetration, damp related (the presence of moisture and/or egress or entry of forms of water and dampness into unintended locations,)
- **D** Material deterioration (rusting, rotting, corrosion, decay) (alteration of the products or elements original intended finish,)
- **E** Operational (not being fit for proper functioning and /or ready for use,)
- **F** Installations & Appearance (inappropriate fitting and finish of a products intended use)



16 Terminology & Their Definitions

ACCESSIBLE AREA - An area of the site where sufficient, safe and reasonable access is available to allow inspection within the scope of the inspection.

ACCESS HOLE - Access hole An opening in flooring or ceiling pr other part of a structure to allow for entry to carry out an inspection.

AGG LINE - A perforated pipe (usually covered with a geo-textile fabric) laid behind retaining walls and other areas to catch seeping stormwater.

APPEARANCE DEFECT - Fault or deviation from the intended appearance of a building element.

ARCHITRAVE - moulding surrounding a door or window opening to cover the join between the frame and the wall finish. BALUSTRADE - A series of vertical members supporting a handrail of a stair, landing, platform or bridge.

BEARER - A sub-floor structural timber member which supports the floor joists.

BRICK VENEER - A method of construction in which a single leaf of non-load bearing wall of brickwork is tied to a timber or metal framed load bearing structure to form the external enclosure.

BUILDING ELEMENT - Portion of a building that, by itself or in combination with other such parts, fulfills a characteristic function. CEMENT - A finely ground inorganic powder that, mixed with water, binds an aggregate / sand mixture into a hard concrete or mortar within a few days.

CLIENT - The person or other entity for whom the inspection is being carried out.

CONCRETE - A conglomerated artificial stone made by mixing in specified proportions cement, water and aggregates and pouring the mixture into prepared forms to set and harden.

CORNICE - A moulding placed at the junction between a wall and ceiling.

DAMP- PROOF COURSE (DPC) - A continuous layer of an impervious material placed in a masonry wall or between a floor and wall to prevent the upward or downward migration of moisture.

DEFECT - Fault or deviation from the intended condition of a material, assembly or component.

DEFLECTION - Has a wavy appearance, causes the feeling of going up or down to these areas stated, lips in concrete surfaces at their joints.

EAVES - The lower part of a roof that overhangs the walls.

FASCIA - A metal profile, which is fixed to the lower ends of rafters and usually supports the guttering.

FOOTING - That part of a construction designed to transfer loads to the supporting foundation, usually constructed of reinforced concrete to support base brickwork.

FOUNDATION - The natural or built-up formation of soil, sub-soil or rock upon which a building or structure is supported. FOUNDATION DOOR ENTRY - The door or cover access point into a dwellings sub floor area.

GABLE - The vertical triangular end of a building with a pitched roof, between the rafters from eaves level to the apex (ridge). It may be formed in brickwork or timber framed and clad with weatherboards.

GAUGE - An indicating device usually in brickwork setting out the number of bricks to a certain measurement.

E.g. 7 brick courses per 600mm in height. This gauge is adjusted to suit the brick and the site conditions.

GOING - In a stair the horizontal distance from the face of one riser to that of the next.

HANGING BEAM - A beam above the ceiling used to support ceiling joists.

HEAD - The upper horizontal member at the top of an opening or frame.

HEADER - A brick laid with its greatest dimension across a wall usually used to tie two skins together or under a door sill or window.

HEARTH - The floor of a fireplace and immediately adjacent area.

HINDERED ACCESS - The inability to access this area stated in this report.

HIP ROOF - A roof which is pyramidal in shape with sloping surfaces and level edges all round.

INSPECTION - Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a reliable conclusion as to the condition of the building.

INSPECTOR - Person of organisation responsible for carrying out the inspection.

JOIST - A timber or steel beam supported by a bearer which the flooring is fixed directly to.



LIMITATION - Any factor that prevents full or proper inspection of the building.

LINTEL - A horizontal supporting member spanning over a window or door opening. A "gal-lintel" is a steel lintel used to support brickwork over an opening.

MANHOLE ENTRY - The entry into the roof loft area by the removal of a ceiling cover or an internal wall doorway.

MAJOR DEFECT - A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.

MINOR DEFECT - A defect other than a major defect.

MORTAR - A mixing of bush sand (white or yellow), cement (grey or off-white) and water for brickwork. Usually at the rate of 6 part sand to one part cement (by volume) and if required one part lime. Can have a flush, raked or round finish.

NEWEL POST - A post at the top or bottom of a stair flight to support the handrail and/or winders in the stair treads

PARAPET - A low wall to protect the edge of a roof, balcony or terrace. Many shops have a parapet at the front of the building for signage.

PARTICLE BOARD - A flat floor sheeting of good dimensional stability made from wood flakes and synthetic resin / binder under heat and pressure. Can be produced with decorative elements for joinery work.

PELMET - A built-in head to a window to conceal the curtain rod or to a sliding door to conceal the tracks. Usually made of wood.

PERP - A vertical joint in masonry construction.

PITCH ROOF - The ratio of the height to span, usually measured in degrees.

POINTING - The completion of jointing between ridge or hip tiles with a matching colour after bedding of tiles or troweling of mortar into joints after bricks have been laid to touch up.

QUAD MOULDING - A moulding with a cross-section of a quadrant of a circle used to cover joints often in eaves or at junctions of walls and/or ceilings.

RAFTER - A sloping member in a roof providing the principal structural support for the roofing material.

RAFTER (COMMON) - A rafter spanning the full distance from the eaves to the ridge.

RAFTER (HIP) - A rafter forming the hip at the external line of intersection of two roof surfaces. Jack rafters meet against it. RAFTER (JACK) - A rafter between a ridge and a valley or a hip rafter and the eave.

RAKED JOINT - A brick joint raked out by the bricklayer for a key for plaster or as a decorative finish.

RENDER - The covering of a brick wall with one or more coats of cement mortar consisting of Sydney Sand, cement and plasterers clay.

RIDGE - The highest part (apex) of a roof, which is usually a horizontal line.

RISER - The vertical face of a step in a stair flight.

SERVICEABILITY DEFECT - Fault or deviation from the intended serviceability performance of a building element. SEPARATION - Gapping formed between the two surfaces stated.

SIGNIFICANT ITEM - An item that is to be reported in accordance with the scope of the inspection.

SKEW NAILING - The driving of nails at an oblique angle often in different directions to improve the strength of a joint of fixing.

SKIRTING - A wooden board fixed to the bottom of a wall at the junction of the floor to prevent damage to the wall or to conceal small gaps.

SLIP JOINT - A joint designed to allow movement between two members usually in the form of two layers of sheet metal with grease installed on top of a brick wall prior to installation of a concrete slab.

SOFFIT/EAVES - The underside of a slab or an eave.

SOLDIER COURSE - A course of brickwork laid on its end.

SPROCKET - A framing timber used in eaves construction.

STRETCHER BOND - The most common masonry bond in Australia in which all bricks are laid with half overlaps and not using half bricks or cross bonds.

STRUCTURAL ELEMENT - Physically distinguishable part of a structure: NOTE: For example a wall, column, beam or connection points.

TERRAZZO - A material consisting of irregular marble or stone fragments set in a matrix of cement and mechanically abraded and polished after casting to produce a smooth hard surface.

THRESHOLD - The step or sill at an external door of usually timber tile or brickwork.

TOUGHENED GLASS - Glass made by rapidly cooling the glass to make it shatter into small pieces when broken for safety, It usually cannot be cut and needs to be made to order to size. It is unlike laminated glass which is made from layers of glass with silicon between to crack only when broken for safety and can easily be cut on site.

UNDERPINNING - The construction of new footings or concrete piers under an existing footing to prevent its collapse or failure.



VALLEY - The meeting line of two inclined roof surfaces at a re-entrant angle.

VALLEY SERIES TRUSSES - A series of timber roof Trusses that form the valley within a hip roof construction. WEEP HOLES - Vertical joints or perpends in brickwork left open above the flashing line to allow water from behind the wall to escape.

PLUMBING AND DRAINAGE TERMS (hjr007)

ABSORPTION TRENCH - A trench, pit or well excavated from permeable ground filled with broken stone, bricks or large granular materials and covered with earth to dispose of the discharge from a septic tank, sullage system or stormwater by absorption into the ground. GULLY TRAP (GT) - An assembly in a sanitary drainage system, consisting of a trap and other fittings. Also called GULLY.

JUNCTION (PIPE) - A pipe fitting incorporating one or more branched.

MANHOLE - A large chamber or opening on a drain, sewer or equipment to permit access for inspection, testing or clearance if obstruction.

STACK - A vertical sanitary drainage pipe, including offsets, which extends more than one story in height. SULLAGE - Domestic waste water other than from soil fixtures.

SUMP - A pit at or below the lowest point of a structure to collect unwanted water and facilitate its removal, usually by means if a SUMP PUMP. Also called DRAIN PIT.

TRAP - a) A fitting usually in the shape of the letter P or S which retains water to form a "water seal" so as to prevent the passage if gases or foul air into the building. b) A fitting for the interception of silt, acids, grease, oils or fats

BOUNDARY TRAP - A trap in the property service drain, usually near the boundary if a property and below the lowest inlet, to prevent the entry of air or gases from the sewer into property service drain. Also called INTERCEPTOR TRAP.

GREASE TRAP - A device in the shape if a box with baffle plates to slow the flow of liquid waste and prevent the passage if greasy substance into the drainage system. Also called GREASE INTERCEPTOR TRAP.

P-TRAP - A trap in which the inlet leg is vertical and the outer leg inclined below the horizontal to specified limits, with or without inspection opening at the lowest point.

S-TRAP - A trap in which the outer leg is vertical and parallel with the inlet leg, with or without inspection opening at the lowest point.

SILT TRAP - A trap containing a removable container for the collection if silt, sand or grit.

VALVE - A device for the control of liquid or gas flow, having an aperture which can be wholly or partially closed by a plate, disc, door, gate, piston, plug ball r the flexing if a diaphragm.

FLOAT VALVE - A valve actuated by a float (floating ball) to control the flow of liquid, used in tanks or cisterns to maintain a minimum water level. Also referred to as FLOATING BALL VALVE.

FLUSH VALVE - A control devise for water flow at mains pressure to a WC pan; used instead of a cistern. MIXING VALVE - A valve which is designed to mix separate supplies of hot and cold water and direct the maximum. PRESSURE REDUCING VALVE - A valve designed to reduce or limit the pressure of a fluid to a predetermined valve in the downstream side. Also called PRESSURE LIMITING VALVE.

PRESSURE RELIEF VALVE - A spring-loaded or weight-controlled automatic valve to limit the build-up of pressure in pipe work, fittings or vessels by discharging excessive pressure to the atmosphere.

STOP VALVE - A valve, such as a gate valve, which can be operated to stop flow in a pipeline. Also known as ISOLATING VALVE.

TEMPERATURE RELIEF - A temperature activated valve to relieve excess pressure in water heaters in the event of a thermostat failure and overheating.

VENT (VENT PIPE) - A pipe provided to limit pressure fluctuations within a discharge pipe system by the induction or discharge of air and/or to facilitate the discharge of gases.



17 General Site Notes

Site Notes and Other Australian Standard AS2870 Requirements to Apply:

Stormwater Drainage & Surface Drainage: All of this properties existing stormwater drainage and connection points and any if applicable surface drainage and or grated inlet drainage points around this dwelling, are to be checked and kept unobstructed and unblocked at all times. We recommend additional or new larger and improved surface inlet and diversion drainage be put into place, if not evident to any low lying or moss effected ground surface areas. For dwellings without visible diversion drainage this drainage must be put into place to prevent further foundation movement to this dwelling and possible destabilisation in the future, or proof by certification is to be provided that an adequate drainage system actually exists on and within this property. It is essential to prevent surface waters from entering the sub floor area of timber floored dwellings to prevent rising damp from causing peaking and cupping to the timber flooring materials. This drainage gives best results once fitted on the high side elevations of this as inspected dwelling or building. (I refer to AS2870 for compliant instructions if required.)

Pitched Roofs: Any pitched roofs with valley gutters and any Dutch gables we recommend that Compraband Press-tite flashings or similar be fitted between the valley gutters and the underside of the roof tiles to prevent future leaking at these points. Valley gutters must be sealed to their top ends to prevent bird or vermin entry into the roof loft area at these points. This flashing can also be required when excessive leaf and or bird entry is clearly visible and is evident within a dwellings roof loft area. High wind areas must have these flashings fitted as high levels of leaf entry into a roof void area can be a fire hazard. (If leaves are found in a roof loft they must be removed.)

Concrete Paths & Driveways: Any concrete paths, concrete slabs or concrete driveways that have been placed directly against any of the dwellings downpipes and or their stormwater drainage points may cause downpipe and stormwater connection slippage over time due to shrinkage within the dwellings foundations. Therefore it is essential these areas be monitored regularly to prevent stormwater leaking and foundation point saturation from occurring. (In normal building practise there must be expansion jointing material placed around the downpipe or stormwater drainage areas before the concrete areas are poured.)

Stored Goods: Any stored goods including building materials like bricks, fire wood stacks etc, around the perimeter of a dwelling are to be removed immediately as they could be harbouring timber pests. See Pest Report for further details. (In the event no Pest Report is being carried out then you must remove these stored goods immediately.) Stored goods within a sub floor area will hinder our inspection and not allow a Purchaser to make an informed decision whether they purchase this property.

Retaining Walls: Referring to retaining walls that are supporting other structures within their vicinity and landscaped retaining walls, more than 700mm high. Where a major defect is identified in any retaining wall regardless of height it is essential that a Structural Engineers Inspection and Report be obtained in relation to the structural integrity of such retaining wall structure. (This report is NOT a structural report and should not be deemed as such under any circumstances.)

Weep Holes: Relating to concrete slab properties and also multi-level properties of brick construction. All of the weep holes are to be left completely exposed, unobstructed and clean at all times. They must be BCA code and Australian Standard compliant in relation to the time as to when the building was first built. Blocked, missing and obscured weep holes can and will cause further dampness problems within the building's interior and within the wall cavity areas. This also includes wall areas above windows and doors are to be BCA code compliant. In recent years weep holes are required to be put into place to the underside of window sills to all windows over .900mm in width and be no more than at 1.2metre centres.

